

VEHICLE INSPECTION REPORT

BN14WTO

Iveco Eurocargo 75E16

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 17/03/2014

Year 2014

Mileage 457,021 Km Warranted

Fuel Type Diesel

Colour RED

VIN ZCFA675B002623248

Body Style Box Van

Service history Yes

Service documents Printout

MOT Due 28/02/2026

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

Tail Lift Cantilever

Tyres

NSF NSI1

OSF OSI1

Spare NSO1

OSO1

NSI2

OSI2

NSO2

OSO2

NSI3

OSI3

NSO3

OSO3

NSI4

OSI4


NSO4



OSO4

Features

- Cruise control
- Cloth seat trim
- Radio/CD
- Front electric windows
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door nsf
Chipped
Multiple Chips



3: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

6: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint

8: Door osf
Dented
With Paint Damage

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		